



Office of the Deputy Conservator
Cochin Port Authority,
W/Island ,Cochin – 682009, KERALA
Phone:0484-2666555/9447460131
website:www.cochinport.gov.in
Email: cfo.copt@cochinport.gov.in

No.MARINE/FS/CFASPCO/9456/2022

Dt.17.03.2026

NOTICE INVITING BUDGETARY OFFER

Subject : Request for Budgetary Quotation – Servicing of 51 Nos. Fire Extinguishers

Cochin Port Authority propose to invite quotations from firms for the pressure testing, painting, refilling, numbering, labelling and commissioning of 51 Nos. of fire extinguishers installed at MULT Jetty and associated locations.

In order to prepare the cost estimates for inviting quotations for the above, Cochin Port now invites budgetary offers from reputed firms for the subject work.

The bidders are requested to submit their budgetary offers excluding GST by email for the subject work as per the Scope of Work & Terms and conditions enumerated below.

The bidders may note that, the offers are invited only for budgetary purpose. Cochin Port is not bound to award the work order to any firms based on the budgetary offer submitted. Cochin Port will not be liable for any financial obligation to the bidders in connection with the preparation of his budgetary offer.

Scope of Work & Terms and conditions

1. The work includes pressure testing, painting, refilling, numbering, labelling and commissioning of 51 Nos. of fire extinguishers of various types installed at different locations.
2. The contractor shall collect the extinguishers from the designated locations, transport them to the servicing facility, carry out the required servicing work and return them to the respective locations after completion.
3. Hydrostatic pressure testing of extinguisher cylinders shall be carried out as per relevant standards.
4. Refilling shall be carried out with the appropriate extinguishing agent depending on the type of extinguisher (DCP, CO2, Mechanical Foam etc.).
5. The extinguisher cylinders shall be cleaned, rust removed and painted with standard fire red colour.
6. Each extinguisher shall be properly numbered and labelled indicating the type, capacity, date of testing/refilling and next due date of servicing.
7. Necessary components such as hoses, valves, safety pins, washers and nozzles shall be checked and replaced wherever required to ensure proper functioning.

8. After completion of servicing, all extinguishers shall be reinstalled at their respective locations and ensured to be in ready-to-use condition.

9. The contractor shall provide service/test certificates confirming that the extinguishers have been serviced and are fit for use.

10. All works shall be carried out in accordance with the the Bureau of Indian Standards and the guidelines of the National Building Code of India.

11. Pressure testing of CO2 cylinders shall be carried out as per the requirements of IS2190 and the provisions of the Gas Cylinders Rules 2016. The testing shall be undertaken only through agencies approved by the Petroleum and Explosives Safety Organisation (PESO). The contractor shall submit the valid test certificate issued by the approved agency along with all other relevant service and test certificates after completion of the work.

Details of Fire Extinguishers

Sl. No	Type of Fire Extinguisher	Capacity	Quantity	Location
1	DCP	50 Kg	2 Nos.	MULT Jetty
2	DCP	75 Kg	10 Nos.	MULT Jetty
3	Mechanical Foam	50 Ltrs	2 Nos.	Pump Room and DG Room
4	DCP	9/10 Kg	22 Nos.	MULT Jetty, Pump Room, Foam Tank Room, Control Room, MULT Manifold, Fuel Station, DG Room, Barge Manifold and Barge Jetty
5	CO2	4.5 Kg	10 Nos.	Pump Room, Foam Tank Room, Both Manifolds, DG Room and Fuel Station
6	Mechanical Foam	9 Ltrs	5 Nos.	Pump Room, DG Room and Fuel Station

Total: **51 Nos.**

You are requested to submit your budgetary quotation along with GST and validity period latest by 25/03/2026 10 AM in the following mail Id

cfo.copt@cochinport.gov.in



CHIEF FIRE OFFICER
COCHIN PORT AUTHORITY